

Oil Field Environmental Incident Summary

Incident: 20161021091024 **Date/Time of Notice:** 10/21/2016 09:10

Responsible Party: Petro Harvester Operating Company, LLC

Well Operator: PETRO HARVESTER OPERATING COMPANY, LLC

Well Name: Busch Trust 06-07 163-92 B

Field Name: PORTAL

Well File #: 31721

Date Incident: 10/20/2016 **Time Incident:** 10:00

Facility ID Number:

County: BURKE

Twp: 164

Rng: 92

Sec: 31

Qtr: SW SE

Location Description:

Submitted By: Gar Watson

Received By:

Contact Person: Mark Bonnie
5851 Legacy Circle, Suite 500
Plano, TX 75024

General Land Use: Cultivated

Affected Medium: Topsoil

Distance Nearest Occupied Building: 17700 Feet

Distance Nearest Water Well: 6100 Feet

Type of Incident: Other

Release Contained in Dike: No

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	3	Barrels	3	Barrels		
Brine	3	Barrels	3	Barrels		

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

No explosive or health hazard risk.

Areal Extent:

150yd long x 50yd wide fine mist fan was released off the well site.

Potential Environmental Impacts:

No impact to surface water or ground water. Majority of released fluids contained on the facility site. 150yd long x 50yd wide fine mist fan was released off the well site.

Action Taken or Planned:

NDIC Field Inspector Jim Potts was notified of the incident telephonically. The affected facility site soil will be scraped up, collected and hauled to an approved disposal facility. The off well site removed soil will be replaced with black dirt to the satisfaction of the surface owner. Piping modifications have been made so that the separator and heater treater will not pressure equalize during ONEOK high line pressures.

Wastes Disposal Location: An approved waste disposal facility.

Agencies Involved:**Updates**

Date: 10/21/2016 **Status:** Reviewed - Follow-up Required

Author: O'Gorman, Brian

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the report, 3 barrels of oil and brine were released and not contained. Further follow-up needed.

Date: 10/25/2016 **Status:** Inspection

Author: Crowder, Kory

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

On location 10/25/2016, at 11:38 a.m. Release off location to the north of flare pit. There is oil staining to cropland in an area of approximately 50 X 40 yards. Follow-up is required to check on vegetation growth.

Date: 11/2/2016 **Status:** Inspection

Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Arrived on location 5:10, 11/2/2016.

Spray to the north of the flare roughly 150 yards. The dike and its side walls appear to have been scraped and the impacted materials removed; however, the field appears to have been left unremediated. Contact responsible party to clarify cleanup intentions on the impacted field.

More follow-up is necessary to ensure proper cleanup.